

CCPC Impoundment "Ashpond" Weekly Inspection

1	Cracks or Bulges	Yes	<input type="radio"/> No	Description	_____
2	Susidence	Yes	<input type="radio"/> No	Description	_____
3	Wet or Soft Soil	<input checked="" type="radio"/> Yes	<input type="radio"/> No	Description	<u>moist area at toe of north embankment</u>
4	Changes in Geometry Elevation of the impounded water and treeboard, 5 depth of sediment and slurry	Yes	<input type="radio"/> No	Description	_____
6	Changes in Vegetation such as being overly lush	Description <u>no change</u>			
7	Obstructive vegetation and trees	Description <u>no change</u>			
8	Animal burrows	Description <u>no change</u>			
9	Changes to liners	Yes	<input type="radio"/> No	Description	_____
10	Spillway Integrity	Not Applicable			
11	Any other changes which may indicate a potential compromise to impoundment integrity	Description <u>no change</u>			
12	Fugitive Dust Issues	Description <u>no change</u>			

Date Inspection Performed 1-19-21

Inspection Performed by Joe Rogers