CCPC Impoundment " Ashpond" Weekly Inspection

| - | 10 | 9 | ∞ | 7 | 6 | ហ | 42 | ω | 2 | دم |
|-------------------------------------|--------------------|-------------------|----------------------|----------------------------------|-------------------------------------------------|------------------------------|----------------------|----------------------|----------------------|--------------------|
| compromise to impoundment integrity | Spillway Integrity | Changes to liners | Animal burrows | Obstructive vegetation and trees | Changes in Vegetation such as being overly lush | depth of sediment and slurry | Changes in Geometry | Wet or Soft Soil | Susidence | Cracks or Bulges |
| Description ANDES | Description NOME | Not Applicable | Yes (No) Description | Description Al One | Description ANN | Description /200110 | Yes (No) Description | Yes (No) Description | Yes (No) Description | Yes No Description |
| | | | ion | | | | on | on | on |)n |

Inspection Performed by Soe Rogers

Register 1

Date Inspection Performed August 27-15